

Drawings


EJA510E, EJA530E Absolute and Gauge Pressure Transmitter

DPharp **EJA**[®]

SD 01C31F01-01EN

Unit: mm (approx. inch)

• With Process connections code 7



*1: Only for EJA530E whose measurement span code is A, B, or C.


*2: 58 mm(2.28 inch) for measurement span code D.

*3: 11 mm(0.43 inch) for measurement span code D.


• With Process connections code 4



• With Process connections code 8 and 9



• Terminal Configuration



• Terminal Wiring

SUPPLY	$\begin{smallmatrix} + \\ - \end{smallmatrix}$	$\begin{smallmatrix} \textcircled{1} \\ \textcircled{2} \end{smallmatrix}$ 	Power supply and output terminals
CHECK	$\begin{smallmatrix} + \\ - \end{smallmatrix}$	$\begin{smallmatrix} \textcircled{3} \\ \textcircled{2} \end{smallmatrix}$ 	External indicator (ammeter) terminals*1*2
			Ground terminal

*1: When using an external indicator or check meter, the internal resistance must be 10 Ω or less.

*2: Not available for FOUNDATION Fieldbus and PROFIBUS PA communication types.